LwWDG

Tilen MAJERLE

May 28, 2023

CONTENTS

1	Features	3		
2	Requirements	5		
3	Contribute			
4				
5	Table of contents5.1Getting started5.2User manual5.3API reference5.4Changelog	14 17		
Index				

Welcome to the documentation for version v1.1.1.

LwWDG is lightweight watchdog library, primarily targeting operating systems, to watch multiple threads and reset system if one of them fails.

Download library Getting started Open Github Donate

ONE

FEATURES

- Written in ANSI C99
- Easy to use very little platform dependency
- Written for operating systems in mind

TWO

REQUIREMENTS

- C compiler
- Few *kB* of non-volatile memory

THREE

CONTRIBUTE

Fresh contributions are always welcome. Simple instructions to proceed:

- 1. Fork Github repository
- 2. Respect C style & coding rules used by the library
- 3. Create a pull request to develop branch with new features or bug fixes

Alternatively you may:

- 1. Report a bug
- 2. Ask for a feature request

FOUR

LICENSE

MIT License

Copyright (c) 2023 Tilen MAJERLE

Permission is hereby granted, free of charge, to any person obtaining a copy of this software and associated documentation files (the "Software"), to deal in the Software without restriction, including without limitation the rights to use, copy, modify, merge, publish, distribute, sublicense, and/or sell copies of the Software, and to permit persons to whom the Software is furnished to **do** so, subject to the following conditions:

The above copyright notice and this permission notice shall be included in all copies or substantial portions of the Software.

THE SOFTWARE IS PROVIDED "AS IS", WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT. IN NO EVENT SHALL THE AUTHORS OR COPYRIGHT HOLDERS BE LIABLE FOR ANY CLAIM, DAMAGES OR OTHER LIABILITY, WHETHER IN AN ACTION OF CONTRACT, TORT OR OTHERWISE, ARISING FROM, OUT OF OR IN CONNECTION WITH THE SOFTWARE OR THE USE OR OTHER DEALINGS IN THE SOFTWARE.

FIVE

TABLE OF CONTENTS

5.1 Getting started

Getting started may be the most challenging part of every new library. This guide is describing how to start with the library quickly and effectively

5.1.1 Download library

Library is primarily hosted on Github.

You can get it by:

- · Downloading latest release from releases area on Github
- Cloning main branch for latest stable version
- Cloning develop branch for latest development

Download from releases

All releases are available on Github releases area.

Clone from Github

First-time clone

This is used when you do not have yet local copy on your machine.

- Make sure git is installed.
- Open console and navigate to path in the system to clone repository to. Use command cd your_path
- Clone repository with one of available options below
 - Run git clone --recurse-submodules https://github.com/MaJerle/lwwdg command to clone entire repository, including submodules
 - Run git clone --recurse-submodules --branch develop https://github.com/MaJerle/ lwwdg to clone development branch, including submodules
 - Run git clone --recurse-submodules --branch main https://github.com/MaJerle/lwwdg to clone *latest stable* branch, including submodules
- Navigate to examples directory and run favourite example

Update cloned to latest version

- Open console and navigate to path in the system where your repository is located. Use command cd your_path
- Run git pull origin main command to get latest changes on main branch
- Run git pull origin develop command to get latest changes on develop branch
- Run git submodule update --init --remote to update submodules to latest version

Note: This is preferred option to use when you want to evaluate library and run prepared examples. Repository consists of multiple submodules which can be automatically downloaded when cloning and pulling changes from root repository.

5.1.2 Add library to project

At this point it is assumed that you have successfully download library, either cloned it or from releases page. Next step is to add the library to the project, by means of source files to compiler inputs and header files in search path

- Copy lwwdg folder to your project, it contains library files
- Add lwwdg/src/include folder to *include path* of your toolchain. This is where *C/C++* compiler can find the files during compilation process. Usually using -I flag
- Add source files from lwwdg/src/ folder to toolchain build. These files are built by *C/C*++ compiler. CMake configuration comes with the library, allows users to include library in the project as **subdirectory** and **library**.
- Copy lwwdg/src/include/lwwdg/lwwdg_opts_template.h to project folder and rename it to lwwdg_opts.h
- Build the project

5.1.3 Configuration file

Configuration file is used to overwrite default settings defined for the essential use case. Library comes with template config file, which can be modified according to needs. and it should be copied (or simply renamed in-place) and named lwwdg_opts.h

Note: Default configuration template file location: lwwdg/src/include/lwwdg/lwwdg_opts_template.h. File must be renamed to lwwdg_opts.h first and then copied to the project directory where compiler include paths have access to it by using #include "lwwdg_opts.h".

List of configuration options are available in the *Configuration* section. If any option is about to be modified, it should be done in configuration file

Listing 1:	Template	configuration	file
------------	----------	---------------	------

lwwdg_opts_template.h

LwWDG configuration file

(continues on next page)

/**

*

* /

* \file

\brief

```
* Copyright (c) 2023 Tilen MAJERLE
7
8
    * Permission is hereby granted, free of charge, to any person
9
    * obtaining a copy of this software and associated documentation
10
    * files (the "Software"), to deal in the Software without restriction.
11
    * including without limitation the rights to use, copy, modify, merge,
12
    * publish, distribute, sublicense, and/or sell copies of the Software,
13
    * and to permit persons to whom the Software is furnished to do so,
14
    * subject to the following conditions:
15
16
    * The above copyright notice and this permission notice shall be
17
    * included in all copies or substantial portions of the Software.
18
19
    * THE SOFTWARE IS PROVIDED "AS IS", WITHOUT WARRANTY OF ANY KIND,
20
    * EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE WARRANTIES
21
    * OF MERCHANTABILITY. FITNESS FOR A PARTICULAR PURPOSE
22
    * AND NONINFRINGEMENT. IN NO EVENT SHALL THE AUTHORS OR COPYRIGHT
23
    * HOLDERS BE LIABLE FOR ANY CLAIM, DAMAGES OR OTHER LIABILITY,
24
    * WHETHER IN AN ACTION OF CONTRACT, TORT OR OTHERWISE, ARISING
25
    * FROM, OUT OF OR IN CONNECTION WITH THE SOFTWARE OR THE USE OR
26
    * OTHER DEALINGS IN THE SOFTWARE.
27
28
    * This file is part of LWWDG - Lightweight watchdog for RTOS in embedded systems.
29
30
    * Author:
                        Tilen MAJERLE <tilen@majerle.eu>
31
    * Version:
                        v1.1.1
32
    */
33
   #ifndef LWWDG_OPTS_HDR_H
34
   #define LWWDG_OPTS_HDR_H
35
36
   /* Rename this file to "lwwdg_opts.h" for your application */
37
38
   /*
39
    * Open "include/lwwdg/lwwdg_opt.h" and
40
    * copy & replace here settings you want to change values
41
    */
42
43
   #endif /* LWWDG_OPTS_HDR_H */
44
```

Note: If you prefer to avoid using configuration file, application must define a global symbol LWWDG_IGNORE_USER_OPTS, visible across entire application. This can be achieved with -D compiler option.

5.2 User manual

LwWDG library is very simple and easy to use. LwWDG was designed to implement software watchdog functionality, primarily used in the operating systems.

Each task in the system defines its very own Watchdog structure, and is responsible to periodically call reload function, while one of the tasks, (it can be) called master task checks the processing function, and reloads hardware watchdog, if everything is fine.

When one of the software watchdogs isn't reloaded within maximum timeout window, main task is not supposed to reload hardware timer anymore. As a consequence, hardware watchdog will reset the system.

Note: This library is designed for operating system, where operations are splitted in the tasks. To ensure stable operation, each task should have a monitoring system.

Since microcontrollers typical utilize single independent watchdog, such solution must be implemented as a combination of hardware and software components.

5.2.1 Platform migration

Library requires atomicity in the processing function, and a milliseconds time source. These should be implemented as macros in the configuration file. Checkout the configuration window or follow to example mentioned below.

5.2.2 Example

A simple example to illustrate functionality.

Listing 2: WIN32 example code

```
#include "lwwdg/lwwdg.h"
1
   #include "windows.h"
2
   #include <stdio.h>
3
   #include <stdlib.h>
4
5
                                                  /* Mutex to simulate interrupt lock */
   HANDLE lwwdg_mutex;
6
   static LARGE_INTEGER freq, sys_start_time; /* Milliseconds time variable */
7
8
   /**
9
    * \brief
                         Get current tick in ms from start of program
10
    * \return
                         uint32_t: Tick in ms
11
    */
12
   uint32 t
13
   sys_get_tick(void) {
14
       LONGLONG ret;
15
       LARGE_INTEGER now;
16
17
       QueryPerformanceFrequency(&freq);
18
       QueryPerformanceCounter(&now);
19
       ret = now.QuadPart - sys_start_time.QuadPart;
20
       return (uint32_t)((ret * 1000) / freq.QuadPart);
21
   }
22
```

(continues on next page)

```
23
   /* Task 1 */
24
   static void
25
   task1(void* arg) {
26
        static lwwdg_wdg_t wdg;
27
        (void)arg;
28
29
       printf("%8u: Task 1 started...\r\n", (unsigned)sys_get_tick());
30
       lwwdg_add(&wdg, 3000);
31
        lwwdg_set_name(&wdg, "task_1_wdg");
32
       while (1) {
33
            /* Periodic reloads... */
34
            lwwdg_reload(&wdg);
35
       }
36
   }
37
38
   /* Task 1 */
39
   static void
40
   task2(void* arg) {
41
        static lwwdg_wdg_t wdg;
42
        (void)arg;
43
44
       printf("%8u: Task 2 started...\r\n", (unsigned)sys_get_tick());
45
       lwwdg_add(&wdg, 5000);
46
       lwwdg_set_name(&wdg, "task_2_wdg");
47
       while (1) {
48
            /* No reload in this task -> consider it failed to run properly */
49
            Sleep(1000);
50
        }
51
   }
52
53
   /**
54
    * \brief
                         Example main function
55
    */
56
   void
57
   example_win32(void) {
58
       DWORD id;
59
60
       QueryPerformanceFrequency(&freq);
61
       QueryPerformanceCounter(&sys_start_time);
62
63
        /* Create lock for lwwdg */
64
       lwwdg_mutex = CreateMutex(NULL, 0, NULL);
65
       lwwdg_init(); /* Init library */
66
67
       /* Start other tasks */
68
       CreateThread(0, 0, (LPTHREAD_START_ROUTINE)task1, NULL, 0, &id);
69
       CreateThread(0, 0, (LPTHREAD_START_ROUTINE)task2, NULL, 0, &id);
70
71
        /* Main task... */
72
       while (1) {
73
            /* Check if all tasks are OK */
74
```

(continues on next page)

```
if (lwwdg_process()) {
75
                printf("%8u: Refreshing hardware watchdog...\r\n", (unsigned)sys_get_tick());
76
                /* TODO: This is where you should reload hardware watchdog */
77
           } else {
78
                printf("%8u: At least one task is out of window -> HW watchdog should not be_
   →reloaded anymore\r\n",
                       (unsigned)sys_get_tick());
80
                break;
81
           }
82
           Sleep(500); /* Make some sleep to offload messages in the WIN32 example */
83
       }
84
       printf("List of expired watchdogs\r\n");
85
       lwwdg_print_expired();
86
       printf("Example completed - a hardware should reset the system now...\r\n");
87
   }
88
```

A corresponding options file, tested for WIN32.

Listing 3: WIN32 LwWDG options file

```
/**
1
    * \file
                        lwwdg_opts_template.h
2
    * \brief
                        LwWDG configuration file
3
    * /
4
5
6
    * Copyright (c) 2023 Tilen MAJERLE
7
8
    * Permission is hereby granted, free of charge, to any person
9
    * obtaining a copy of this software and associated documentation
10
    * files (the "Software"), to deal in the Software without restriction,
11
    * including without limitation the rights to use, copy, modify, merge,
12
    * publish, distribute, sublicense, and/or sell copies of the Software,
13
    * and to permit persons to whom the Software is furnished to do so,
14
    * subject to the following conditions:
15
16
    * The above copyright notice and this permission notice shall be
17
    * included in all copies or substantial portions of the Software.
18
19
    * THE SOFTWARE IS PROVIDED "AS IS", WITHOUT WARRANTY OF ANY KIND,
20
    * EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE WARRANTIES
21
    * OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE
22
    * AND NONINFRINGEMENT. IN NO EVENT SHALL THE AUTHORS OR COPYRIGHT
23
    * HOLDERS BE LIABLE FOR ANY CLAIM, DAMAGES OR OTHER LIABILITY,
24
    * WHETHER IN AN ACTION OF CONTRACT, TORT OR OTHERWISE, ARISING
25
    * FROM. OUT OF OR IN CONNECTION WITH THE SOFTWARE OR THE USE OR
26
    * OTHER DEALINGS IN THE SOFTWARE.
27
28
    * This file is part of LWWDG - Lightweight watchdog for RTOS in embedded systems.
29
30
    * Author:
                        Tilen MAJERLE <tilen@majerle.eu>
31
    * Version:
                        v1.1.1
32
```

```
*/
33
   #ifndef LWWDG_HDR_OPTS_H
34
   #define LWWDG_HDR_OPTS_H
35
36
   #include <stdio.h>
37
38
   /* Win32 port */
39
   #include "windows.h"
40
   extern uint32_t sys_get_tick(void); /* Milliseconds tick is available externally */
41
                                             /* Mutex is defined and initialized externally */
   extern HANDLE lwwdg_mutex;
42
43
   #define LWWDG_CRITICAL_SECTION_DEFINE /* Nothing to do here... */
44
   #define LWWDG_CRITICAL_SECTION_LOCK()
45
                                                                                                     ш
                                       ١
    \rightarrow 
       do {
46
                                                                                                     <u>ц</u>
                                       \
   WaitForSingleObject(lwwdg_mutex, INFINITE);
47
                                                                                                     . .
                                       \
   } while (0)
48
   #define LWWDG_CRITICAL_SECTION_UNLOCK()
                                                    ReleaseMutex(lwwdg_mutex)
49
   #define LWWDG_GET_TIME()
                                                    sys_get_tick()
50
51
   #define LWWDG_CFG_ENABLE_WDG_NAME
                                                    1
52
   #define LWWDG_CFG_WDG_NAME_ERR_DEBUG(_wdg_) printf("Watchdog %s failed to reload in time!
53
   \rightarrow \r\n", (_wdg_))
54
   #endif /* LWWDG_HDR_OPTS_H */
55
```

5.3 API reference

List of all the modules:

5.3.1 LwWDG

```
group LWWDG
```

Lightweight watchdog for RTOS in embedded systems.

Functions

uint8_t lwwdg_init(void)

Initialize watchdog module.

Returns 1 on success, 0 otherwise

uint8_t lwwdg_add(lwwdg_wdg_t *wdg, uint32_t timeout)

Add new watchdog timer instance to internal linked list.

Parameters

• wdg – Watchdog handle. Must not be local variable

• timeout - Max allowed timeout in milliseconds

Returns 1 on success, **0** otherwise

uint8_t lwwdg_remove(lwwdg_wdg_t *wdg)

Remove watchdog from the list.

This function is typically used if a task is killed by the scheduler. A user must manually call the function and can later clean wdg memory

Parameters wdg - Watchdog handle to remove from list

Returns 1 if removed, **0** otherwise

uint8_t lwwdg_reload(lwwdg_wdg_t *wdg)

Reload thread watchdog.

Note: Reload will not be successful, if there was a timeout before. This will ensure that main thread won't reload hardware watchdog, resulting system to reset

Parameters wdg – Watchdog handle to reload

Returns 1 on success, 0 otherwise

uint8_t lwwdg_process(void)

Process and check system timers.

Function will check all timers and will return OK, if all timers are within max timeout state

Returns 1 if hardware watchdog can be reset, **0** if at least one timer hasn't been reloaded within maximum timeout

void lwwdg_set_name(lwwdg_wdg_t *wdg, const char *name)

Set the watchdog name for debug reasons.

Note: Available only when *LWWDG_CFG_ENABLE_WDG_NAME* is enabled

Parameters

- wdg Watchdog instance
- **name** Pointer to the constant string for the name. String is not copied, rather only pointer is set

void lwwdg_print_expired(void)

Print all expired watchdogs.

Note: *LWWDG_CFG_ENABLE_WDG_NAME* and *LWWDG_CFG_WDG_NAME_ERR_DEBUG* must be enabled and implemented

struct lwwdg_wdg_t

#include <lwwdg.h> Watchdog structure.

Public Members

struct lwwdg_wdg ***next** Next entry on a list

uint32_t **timeout** Timeout in milliseconds

uint32_t last_reload_time Last reload time in milliseconds

const char ***name**

Pointer to constant string indicating watchdog name

5.3.2 Configuration

This is the default configuration of the middleware. When any of the settings shall be modified, it shall be done in dedicated application config lwwdg_opts.h file.

Note: Check *Getting started* to create configuration file.

group LWWDG_OPT

Default configuration setup.

Defines

LWWDG_CFG_ENABLE_WDG_NAME

Enables or disables field in wdg structure to contain watchdog name.

This can be useful for debugging purposes

LWWDG_CFG_WDG_NAME_ERR_DEBUG(_wdg_name_)

Macro called if LWWDG_CFG_ENABLE_WDG_NAME is enabled and if watchdog error occurs.

It can be overwritten by the application to print watchdog name.

Parameters

• wdg_name - [in] Watchdog name as defined by *lwwdg_set_name* function

LWWDG_GET_TIME()

Get system time in milliseconds.

It is required to keep reload time

LWWDG_CRITICAL_SECTION_DEFINE

Define the critical section.

Used at the beinning of the function, to define potential local variable to keep status of critical section (if already locked)

Note: Default implementation is for *Cortex-M*

LWWDG_CRITICAL_SECTION_LOCK()

Lock the critical section.

Critical section should prevent other tasks or interrupt, to access to the same core.

Easiest is to simply disable the interrupt, since task is normally pretty quick.

Note: Default implementation is for *Cortex-M*

LWWDG_CRITICAL_SECTION_UNLOCK()

Unlock the critical section.

Note: Default implementation is for *Cortex-M*

5.4 Changelog

```
# Changelog
## Develop
## v1.1.1
- Fix wrong time check
## v1.1.0
- Print erro0 message only on one trial
- Add print option to list all expired watchdogs
## v1.0.0
- Added option to remove wdg from the list
- Added option to set watchdog name and print its name on error
## v0.0.1
- First version
****
```

INDEX

L

lwwdg_add (C++ function), 17 LWWDG_CFG_ENABLE_WDG_NAME (C macro), 19 LWWDG_CFG_WDG_NAME_ERR_DEBUG (C macro), 19 LWWDG_CRITICAL_SECTION_DEFINE (C macro), 19 LWWDG_CRITICAL_SECTION_LOCK (C macro), 20 LWWDG_CRITICAL_SECTION_UNLOCK (C macro), 20 LWWDG_GET_TIME (C macro), 19 lwwdg_init (C++ function), 17 lwwdg_print_expired (C++ function), 18 lwwdg_process (C++ function), 18 lwwdg_reload (C++ function), 18 lwwdg_remove (C++ function), 18 lwwdg_set_name (C++ function), 18 lwwdg_wdg_t (C++ struct), 18 lwwdg_wdg_t::last_reload_time(C++ member), 19 lwwdg_wdg_t::name (C++ member), 19 lwwdg_wdg_t::next (C++ member), 19 lwwdg_wdg_t::timeout (C++ member), 19